



Leica FireCam

**Release Notes V 3.3.1**

*Leica*  
MICROSYSTEMS

---

# Leica FireCam

## Release Notes V3.3.1

### Abstract

This document describes the V 3.3.1 release of Leica FireCam software for Apple Mac Intel or PowerPC computers.

All reasonable steps have been taken to ensure that this publication is correct and complete, but should any user be in doubt about any detail, clarification may be sought from Leica Microsystems (Switzerland) Ltd, or their accredited representative. The information in this document is subject to change without notice and should not be construed as a commitment by Leica Microsystems (Switzerland) Ltd.

Leica Microsystems (Switzerland) Ltd. accepts no responsibility for any errors that may appear in this document.

© Leica Microsystems (Switzerland) Ltd, 2008.

**All rights reserved. The contents of this publication may not be reproduced in any form, or communicated to a third party without prior written permission of Leica Microsystems (Switzerland) Ltd.**

Due to a policy of continuous development, we reserve the right to change specifications without notice.

Apple, Mac, Macintosh and FireWire are trademarks of Apple Computer Inc.

Date: November 2008

---

# Table of Contents

<b>1</b>	<b>Introduction</b>	<b>4</b>
<b>2</b>	<b>Installation</b>	<b>4</b>
<b>3</b>	<b>Reason for this Release</b>	<b>4</b>
<b>4</b>	<b>System Requirements</b>	<b>5</b>
4.1	Operating System.....	5
4.2	Computer.....	5
<b>5</b>	<b>Changes in This Release</b>	<b>6</b>
5.1	Fixes in 3.3.1.....	6
<b>6</b>	<b>Changes in Previous Releases</b>	<b>7</b>
6.1	Features in 3.3.0.....	7
6.2	Features in 3.2.0.....	7
6.3	Fixes in 3.2.0.....	7
6.4	Features in 3.1.0.....	7
6.5	Features in 3.0.1.....	7
6.6	Features in 3.0.0.....	7
6.7	Features in 2.0.1.....	7
6.8	Features in 2.0.0.....	8
<b>7</b>	<b>Known Limitations</b>	<b>9</b>
7.1	USB1.....	9
7.2	MacOS 10.4.8 (Tiger).....	9
7.3	Older Leica DFC cameras.....	9

---

# 1 Introduction

This release supports the following Leica cameras and microscopes.

You should read this document before installing your copy of this software.

- DFC280
- DFC290
- DFC320
- DFC300 FX
- DFC310 FX
- DFC340 FX
- DFC350 FX
- DFC360 FX
- DFC420
- DFC420 C
- DFC480
- DFC490
- IC D
- IC 3D
- DFC500
- EC3
- EZ4 D Stereomicroscope

**Please identify the type of camera or microscope that you are using before installing the software from this release.**

If in doubt, check for the software specific to your equipment at the Leica Microsystems websites:

[www.leica-microsystems.com/camera\\_systems](http://www.leica-microsystems.com/camera_systems)

(for Leica DFC cameras)

or

[www.leica-microsystems.com/education](http://www.leica-microsystems.com/education)

(for Leica EZ4 D stereomicroscopes & EC3 cameras)

## 2 Installation

Installation and operation of the software is detailed in the Leica FireCam User Manual and Leica FireCam Help. The manual can also be found on the CD.

Upon inserting the CD into your computer you should be presented with options to install the software or browse to the supporting documentation on the CD.

## 3 Reason for this Release

This version is a bug fix for the EC3 camera.

## 4 System Requirements

### 4.1 Operating System

Supported MacOS operating systems (32-bit & 64-bit):

10.4 (Tiger) or later.

Please use the latest updates. (Please see the [limitations.](#))

(contact <http://www.apple.com> for updating your system)

You may need Administrative rights for installation.

### 4.2 Computer

The recommended computer specification is as follows:

- G4 PowerPC or Intel processor 1Ghz Mac, with 512 Mb RAM.
- Graphics: 128Mb RAM supporting 32 bit.
- 1394a FireWire Port for all Leica DFC cameras, 1394a or 1394b for Leica DFC310 FX and DFC360 FX.
- USB 2.0 port (for EC3 camera or EZ4 D microscope)
- CD-ROM drive or internet connection for download.

**Please Note:**

Faster processors, additional RAM memory and more advanced graphics adapters may improve the performance of Leica FireCam. Running other programs at the same time may limit performance.

## 5 Changes in This Release

### 5.1 Fixes in 3.3.1

Leica EC3: After capture, the frame rates sometimes slowed when used on Mac OS v10.5 (Leopard). This is fixed.

## 6 Changes in Previous Releases

### 6.1 Features in 3.3.0

Leica DFC310 FX: This version introduces support for DFC310FX. This camera has a 1394b (800 Mb/s) FireWire connector, but can run on an existing 1394a port with an A->B cable.

### 6.2 Features in 3.2.0

Leica DFC360 FX: This version introduces support for DFC360FX. This camera has a 1394b (800 Mb/s) FireWire connector, but can run on an existing 1394a port with an A->B cable.

64-bit: Mac OS 64-bit is supported.

10.3 (Panther): This operating system is no longer supported.

### 6.3 Fixes in 3.2.0

Histogram: Fixed gaps in the display.

JPEG & PNG file format: Fixed rotate and flip.

Auto-exposure: This was not refreshed upon recalling from a saved setting. This is fixed.

Output Filename: This was not recalled from a saved setting. This is fixed.

Leica DFC300/350 FX: Supports early models of this camera.

### 6.4 Features in 3.1.0

External Editor: Provides an option to open images automatically in an external editor after capture.

Supports Full Screen mode.

### 6.5 Features in 3.0.1

FireCam now supports Leica DFC500 cameras on computers with Intel processors. Please see the [limitations](#).

### 6.6 Features in 3.0.0

FireCam now supports Leica DFC cameras on computers with Intel processors.

Introduces support for Leica DFC290 and Leica DFC420 C cameras.

### 6.7 Features in 2.0.1

FireCam now supports computers with Intel processors.

## **6.8 Features in 2.0.0**

This is the first release of the software for Leica EZ4 D Stereomicroscopes.



## 7 Known Limitations

### 7.1 USB1

USB 1.0 or 1.1 (Standard USB) are not supported in Leica FireCam. Your computer must support USB 2.0 (High-Speed USB) to use the Leica EZ4 D or Leica EC3 correctly.

### 7.2 MacOS 10.4.8 (Tiger)

The Leica DFC500 does not operate in this specific version of Mac OS. Use 10.4.9 or higher.

### 7.3 Older Leica DFC cameras

The following Leica cameras are not supported:

DFC300/F  
DFC350F  
DC500

Leica Microsystems (Switzerland) Ltd  
Stereo and Macroscopic Systems  
CH 9435 Heerbrugg  
Switzerland

Customer Support Tel: +44 1223 401824  
Fax: +44 1223 412526  
[di.support@leica-microsystems.com](mailto:di.support@leica-microsystems.com)  
[www.leica-microsystems.com](http://www.leica-microsystems.com)

